



DBCI DOORS

4645 Timber Ridge Dr. Suite 250
Douglasville, GA 30135


PHONE (888) 679-1066

www.dbc.com

SHAFT HOIST WITH SPACER

Rev. Date: 9/29/2022


810040-0000



4:1 SHAFT HOIST

IMPACT DRIVER WARNING!

DO NOT OVER TIGHTEN BOLTS. OVERTIGHTENING OF BOLTS WILL RESULT IN DAMAGE TO ASSEMBLY.



8:1 SHAFT HOIST

IMPORTANT INFORMATION

DBCI DOORS MUST BE INSTALLED BY TRAINED ROLLING DOOR TECHNICIANS QUALIFIED TO INSTALL PRODUCT SAFELY WITH PROPER KNOWLEDGE, TOOLS, SAFETY AND INSTALLATION EQUIPMENT. CAREFULLY READ INSTALLATION INSTRUCTIONS. FAMILIARIZE YOURSELF WITH ALL INSTALLATION PROCEDURES, WARNINGS, CAUTIONS, AND NOTES BEFORE ATTEMPTING TO INSTALL DOOR. DBCI WILL NOT WARRANTY OR ACCEPT RESPONSIBILITY FOR DOORS NOT INSTALLED PER THESE INSTALLATION INSTRUCTIONS.